


TEST RESULTS

Alternative Technologies, Inc.
 12350 River Ridge Blvd.
 Burnsville, MN 55337
 Telephone (800) 255-8656 or (952) 894-3455

PCB CONTENT USEPA METHOD 8082

Linda Johnson
 Salt River Project
 P.O. Box 52025, XCT310
 Phoenix, AZ 86072-2025



Report Date: 19-May-06

Date Received: 5-Apr-06

Arizona Lab License Number: AZ0626

| SAMPLE IDENTIFICATION | | LABORATORY NUMBER | AROCLOP | RESULTS |
|--------------------------|------------------------------------|-------------------|---------|---------|
| S/N: 45121 CO#: 46512 | 12317 Date Analyzed: 04/27/2006 | 136471-001 | | <1 ppm |
| S/N: 81777 CO#: 46514 | 12317 Date Analyzed: 04/27/2006 | 136471-002 | | <1 ppm |
| S/N: 33998 CO#: 46515 | 12317 Date Analyzed: 04/27/2006 | 136471-003 | 1260 | 30 ppm |
| S/N: 30820 CO#: 46517 | 12317 Date Analyzed: 04/27/2006 | 136471-004 | | <1 ppm |
| S/N: 27327 CO#: 46518 | 12317 Date Analyzed: 04/27/2006 | 136471-005 | 1260 | 2 ppm |
| S/N: 88902 CO#: 46520 | 12317 Date Analyzed: 04/27/2006 | 136471-006 | | <1 ppm |
| S/N: 61223 CO#: 46521 | 12317 Date Analyzed: 04/27/2006 | 136471-007 | | <1 ppm |
| S/N: 63352 CO#: 48112 | 12317 Date Analyzed: 04/27/2006 | 136471-008 | | <1 ppm |
| S/N: 90853 CO#: 48114 | 12317 Date Analyzed: 04/27/2006 | 136471-009 | | <1 ppm |
| S/N: 67453 CO#: 48111 | 12317 Date Analyzed: 04/27/2006 | 136471-010 | 1260/42 | 12 ppm |

Alternative Technologies, Inc., (ATI) shall assume no liability or responsibility, nor imply or express any warranty or other security against client loss of production, operation, profitability, or other loss, regardless of circumstances, beyond the cost of re-analysis by ATI.

Approved by: 

TEST RESULTS

Alternative Technologies, Inc.
12350 River Ridge Blvd.
Burnsville, MN 55337
Telephone (800) 255-8656 or (952) 894-3455

PCB CONTENT USEPA METHOD 8082

Linda Johnson
Salt River Project
P.O. Box 52025, XCT310
Phoenix, AZ 86072-2025

Report Date: 19-May-06

Date Received: 5-Apr-06

Arizona Lab License Number: AZ0626

| SAMPLE IDENTIFICATION | | LABORATORY NUMBER | AROCLOP | RESULTS |
|---------------------------|------------------------------------|-------------------|---------|---------|
| S/N: 67008 CO#: 48099 | 12317 Date Analyzed: 04/27/2006 | 136471-011 | | <1 ppm |
| S/N: 98147 CO#: 48100 | 12317 Date Analyzed: 04/27/2006 | 136471-012 | | <1 ppm |
| S/N: 100698 CO#: 48109 | 12317 Date Analyzed: 04/27/2006 | 136471-013 | | <1 ppm |
| S/N: 88578 CO#: 48116 | 12317 Date Analyzed: 04/27/2006 | 136471-014 | | <1 ppm |
| S/N: 102403 CO#: 48107 | 12317 Date Analyzed: 04/27/2006 | 136471-015 | | <1 ppm |
| S/N: 20772 CO#: 43743 | 12317 Date Analyzed: 04/27/2006 | 136471-016 | 1260 | 14 ppm |
| S/N: 92475 CO#: 43744 | 12317 Date Analyzed: 04/27/2006 | 136471-017 | | <1 ppm |
| S/N: 37243 CO#: 48063 | 12317 Date Analyzed: 04/27/2006 | 136471-018 | | <1 ppm |
| S/N: 40649 CO#: 48062 | 12317 Date Analyzed: 04/27/2006 | 136471-019 | | <1 ppm |
| S/N: 30489 CO#: 48064 | 12317 Date Analyzed: 04/27/2006 | 136471-020 | | <1 ppm |

Alternative Technologies, Inc., (ATI) shall assume no liability or responsibility, nor imply or express any warranty or other security against client loss of production, operation, profitability, or other loss, regardless of circumstances, beyond the cost of re-analysis by ATI.

Approved by: _____



TEST RESULTS

Alternative Technologies, Inc.

12350 River Ridge Blvd.

Burnsville, MN 55337

Telephone (800) 255-8656 or (952) 894-3455

PCB CONTENT USEPA METHOD 8082

Linda Johnson
Salt River Project
P.O. Box 52025, XCT310
Phoenix, AZ 86072-2025

Report Date: 19-May-06


Date Received: 5-Apr-06

Arizona Lab License Number: AZ0626

| SAMPLE IDENTIFICATION | | LABORATORY NUMBER | AROCLOR | RESULTS |
|---------------------------|------------------------------------|-------------------|---------|---------|
| S/N: 94037 CO#: 48065 | 12317 Date Analyzed: 04/27/2006 | 136471-021 | | <1 ppm |
| S/N: 67927 CO#: 48308 | 12317 Date Analyzed: 04/27/2006 | 136471-022 | 1260/42 | 9 ppm |
| S/N: 93042 CO#: 48310 | 12317 Date Analyzed: 04/27/2006 | 136471-023 | | <1 ppm |
| S/N: 99699 CO#: 48311 | 12317 Date Analyzed: 04/27/2006 | 136471-024 | | <1 ppm |
| S/N: 99698 CO#: 48312 | 12317 Date Analyzed: 04/27/2006 | 136471-025 | | <1 ppm |
| S/N: 90848 CO#: 48313 | 12317 Date Analyzed: 04/27/2006 | 136471-026 | | <1 ppm |
| S/N: 90926 CO#: 48314 | 12317 Date Analyzed: 04/27/2006 | 136471-027 | | <1 ppm |
| S/N: 90849 CO#: 48315 | 12317 Date Analyzed: 04/27/2006 | 136471-028 | | <1 ppm |
| S/N: 100200 CO#: 48316 | 12317 Date Analyzed: 04/27/2006 | 136471-029 | | <1 ppm |
| S/N: 102968 CO#: 48317 | 12317 Date Analyzed: 04/27/2006 | 136471-030 | | <1 ppm |

Alternative Technologies, Inc., (ATI) shall assume no liability or responsibility, nor imply or express any warranty or other security against client loss of production, operation, profitability, or other loss, regardless of circumstances, beyond the cost of re-analysis by ATI.

Approved by: _____



TEST RESULTS

Alternative Technologies, Inc.
12350 River Ridge Blvd.
Burnsville, MN 55337
Telephone (800) 255-8656 or (952) 894-3455

PCB CONTENT USEPA METHOD 8082

Linda Johnson
Salt River Project
P.O. Box 52025, XCT310
Phoenix, AZ 86072-2025

Report Date: 19-May-06


Date Received: 5-Apr-06

Arizona Lab License Number: AZ0626

| SAMPLE IDENTIFICATION | | LABORATORY NUMBER | AROCLOLOR | RESULTS |
|---------------------------|------------------------------------|-------------------|-----------|---------|
| S/N: 96331 CO#: 48318 | 12317 Date Analyzed: 04/27/2006 | 136471-031 | 1260/42 | 14 ppm |
| S/N: 100390 CO#: 48319 | 12317 Date Analyzed: 04/27/2006 | 136471-032 | | <1 ppm |
| S/N: 100705 CO#: 48320 | 12317 Date Analyzed: 04/27/2006 | 136471-033 | | <1 ppm |
| S/N: 90795 CO#: 48321 | 12317 Date Analyzed: 04/27/2006 | 136471-034 | 1260 | 7 ppm |
| S/N: 88359 CO#: 48323 | 12317 Date Analyzed: 04/27/2006 | 136471-035 | | <1 ppm |
| S/N: 99680 CO#: 48324 | 12317 Date Analyzed: 04/27/2006 | 136471-036 | | <1 ppm |
| S/N: 99678 CO#: 48325 | 12317 Date Analyzed: 04/27/2006 | 136471-037 | | <1 ppm |
| S/N: 99399 CO#: 48322 | 12317 Date Analyzed: 04/27/2006 | 136471-038 | | <1 ppm |
| S/N: 86493 CO#: 48295 | 12317 Date Analyzed: 04/27/2006 | 136471-039 | | <1 ppm |
| S/N: 92132 CO#: 48296 | 12317 Date Analyzed: 04/27/2006 | 136471-040 | | <1 ppm |

Alternative Technologies, Inc., (ATI) shall assume no liability or responsibility, nor imply or express any warranty or other security against client loss of production, operation, profitability, or other loss, regardless of circumstances, beyond the cost of re-analysis by ATI.

Approved by: _____



TEST RESULTS

Alternative Technologies, Inc.
12350 River Ridge Blvd.
Burnsville, MN 55337
Telephone (800) 255-8656 or (952) 894-3455

PCB CONTENT USEPA METHOD 8082

Linda Johnson
Salt River Project
P.O. Box 52025, XCT310
Phoenix, AZ 86072-2025

Report Date: 19-May-06


Date Received: 5-Apr-06

Arizona Lab License Number: AZ0626

| SAMPLE IDENTIFICATION | | LABORATORY NUMBER | AROC LOR | RESULTS |
|--------------------------|------------------------------------|-------------------|----------|---------|
| S/N: 94033 CO#: 48297 | 12317 Date Analyzed: 04/27/2006 | 136471-041 | | <1 ppm |
| S/N: 85901 CO#: 48299 | 12317 Date Analyzed: 04/27/2006 | 136471-042 | | <1 ppm |
| S/N: 97946 CO#: 48301 | 12317 Date Analyzed: 04/27/2006 | 136471-043 | | <1 ppm |
| S/N: 92211 CO#: 48302 | 12317 Date Analyzed: 04/27/2006 | 136471-044 | | <1 ppm |
| S/N: 84768 CO#: 48303 | 12317 Date Analyzed: 04/27/2006 | 136471-045 | | <1 ppm |
| S/N: 84762 CO#: 48304 | 12317 Date Analyzed: 04/27/2006 | 136471-046 | | <1 ppm |
| S/N: 84770 CO#: 48305 | 12317 Date Analyzed: 04/27/2006 | 136471-047 | | <1 ppm |
| S/N: 98078 CO#: 48306 | 12317 Date Analyzed: 04/27/2006 | 136471-048 | | <1 ppm |
| S/N: 62733 CO#: 48143 | 12317 Date Analyzed: 04/27/2006 | 136471-049 | | <1 ppm |
| S/N: 78502 CO#: 48144 | 12317 Date Analyzed: 04/27/2006 | 136471-050 | | <1 ppm |

Alternative Technologies, Inc., (ATI) shall assume no liability or responsibility, nor imply or express any warranty or other security against client loss of production, operation, profitability, or other loss, regardless of circumstances, beyond the cost of re-analysis by ATI.

Approved by: _____



TEST RESULTS

Alternative Technologies, Inc.
12350 River Ridge Blvd.
Burnsville, MN 55337
Telephone (800) 255-8656 or (952) 894-3455

PCB CONTENT USEPA METHOD 8082

Linda Johnson
Salt River Project
P.O. Box 52025, XCT310
Phoenix, AZ 86072-2025

Report Date: 19-May-06


Date Received: 5-Apr-06

Arizona Lab License Number: AZ0626

| SAMPLE IDENTIFICATION | | LABORATORY NUMBER | AROCLOLOR | RESULTS |
|--------------------------|------------------------------------|-------------------|-----------|---------|
| S/N: 79184 CO#: 48145 | 12317 Date Analyzed: 04/27/2006 | 136471-051 | | <1 ppm |
| S/N: 99915 CO#: 48146 | 12317 Date Analyzed: 04/27/2006 | 136471-052 | | <1 ppm |
| S/N: 94051 CO#: 48255 | 12317 Date Analyzed: 04/27/2006 | 136471-053 | | <1 ppm |
| S/N: 97944 CO#: 48256 | 12317 Date Analyzed: 04/27/2006 | 136471-054 | | <1 ppm |
| S/N: 98041 CO#: 48257 | 12317 Date Analyzed: 04/27/2006 | 136471-055 | | <1 ppm |
| S/N: 93987 CO#: 48258 | 12317 Date Analyzed: 04/27/2006 | 136471-056 | | <1 ppm |
| S/N: 96299 CO#: 48259 | 12317 Date Analyzed: 04/27/2006 | 136471-057 | | <1 ppm |
| S/N: 62694 CO#: 48140 | 12317 Date Analyzed: 04/27/2006 | 136471-058 | | <1 ppm |
| S/N: 63063 CO#: 48141 | 12317 Date Analyzed: 04/27/2006 | 136471-059 | | <1 ppm |
| S/N: 99270 CO#: 48142 | 12317 Date Analyzed: 04/27/2006 | 136471-060 | | <1 ppm |

Alternative Technologies, Inc., (ATI) shall assume no liability or responsibility, nor imply or express any warranty or other security against client loss of production, operation, profitability, or other loss, regardless of circumstances, beyond the cost of re-analysis by ATI.

Approved by: _____



TEST RESULTS

Alternative Technologies, Inc.
12350 River Ridge Blvd.
Burnsville, MN 55337
Telephone (800) 255-8656 or (952) 894-3455

PCB CONTENT USEPA METHOD 8082

Linda Johnson
Salt River Project
P.O. Box 52025, XCT310
Phoenix, AZ 86072-2025

Report Date: 19-May-06


Date Received: 5-Apr-06

Arizona Lab License Number: AZ0626

| SAMPLE IDENTIFICATION | | LABORATORY NUMBER | AROCLOR | RESULTS |
|---------------------------|------------------------------------|-------------------|---------|---------|
| S/N: 101187 CO#: 48275 | 12317 Date Analyzed: 04/27/2006 | 136471-061 | | <1 ppm |
| S/N: 100730 CO#: 48276 | 12317 Date Analyzed: 04/27/2006 | 136471-062 | | <1 ppm |
| S/N: 92382 CO#: 48277 | 12317 Date Analyzed: 04/27/2006 | 136471-063 | | <1 ppm |
| S/N: 94107 CO#: 48264 | 12317 Date Analyzed: 04/27/2006 | 136471-064 | | <1 ppm |
| S/N: 85885 CO#: 48266 | 12317 Date Analyzed: 04/27/2006 | 136471-065 | | <1 ppm |
| S/N: 98087 CO#: 48267 | 12317 Date Analyzed: 04/27/2006 | 136471-066 | | <1 ppm |
| S/N: 98089 CO#: 48270 | 12317 Date Analyzed: 04/27/2006 | 136471-067 | | <1 ppm |
| S/N: 92007 CO#: 48271 | 12317 Date Analyzed: 04/27/2006 | 136471-068 | | <1 ppm |
| S/N: 93978 CO#: 48272 | 12317 Date Analyzed: 04/27/2006 | 136471-069 | | <1 ppm |
| S/N: 97814 CO#: 48261 | 12317 Date Analyzed: 04/27/2006 | 136471-070 | | <1 ppm |

Alternative Technologies, Inc., (ATI) shall assume no liability or responsibility, nor imply or express any warranty or other security against client loss of production, operation, profitability, or other loss, regardless of circumstances, beyond the cost of re-analysis by ATI.

Approved by: _____



TEST RESULTS

Alternative Technologies, Inc.
12350 River Ridge Blvd.
Burnsville, MN 55337
Telephone (800) 255-8656 or (952) 894-3455

PCB CONTENT USEPA METHOD 8082

Linda Johnson
Salt River Project
P.O. Box 52025, XCT310
Phoenix, AZ 86072-2025

Report Date: 19-May-06

Date Received: 5-Apr-06

Arizona Lab License Number: AZ0626

| SAMPLE IDENTIFICATION | | LABORATORY NUMBER | AROCLOP | RESULTS |
|---------------------------|------------------------------------|-------------------|---------|---------|
| S/N: 86134 CO#: 48262 | 12317 Date Analyzed: 04/27/2006 | 136471-071 | | <1 ppm |
| S/N: 98020 CO#: 48263 | 12317 Date Analyzed: 04/27/2006 | 136471-072 | | <1 ppm |
| S/N: 93889 CO#: 48273 | 12317 Date Analyzed: 04/27/2006 | 136471-073 | | <1 ppm |
| S/N: 93973 CO#: 48274 | 12317 Date Analyzed: 04/27/2006 | 136471-074 | | <1 ppm |
| S/N: 47485 CO#: 44337 | 12317 Date Analyzed: 04/27/2006 | 136471-075 | | <1 ppm |
| S/N: 46790 CO#: 47575 | 12317 Date Analyzed: 04/27/2006 | 136471-076 | 1260 | 20 ppm |
| S/N: 51062 CO#: 47576 | 12317 Date Analyzed: 04/27/2006 | 136471-077 | | <1 ppm |
| S/N: 98270 CO#: 48134 | 12317 Date Analyzed: 04/27/2006 | 136471-078 | | <1 ppm |
| S/N: 87067 CO#: 48137 | 12317 Date Analyzed: 04/27/2006 | 136471-079 | | <1 ppm |
| S/N: 100707 CO#: 48455 | 12317 Date Analyzed: 04/27/2006 | 136471-080 | | <1 ppm |

Alternative Technologies, Inc., (ATI) shall assume no liability or responsibility, nor imply or express any warranty or other security against client loss of production, operation, profitability, or other loss, regardless of circumstances, beyond the cost of re-analysis by ATI.

Approved by: _____



TEST RESULTS

Alternative Technologies, Inc.
12350 River Ridge Blvd.
Burnsville, MN 55337
Telephone (800) 255-8656 or (952) 894-3455

PCB CONTENT USEPA METHOD 8082

Linda Johnson
Salt River Project
P.O. Box 52025, XCT310
Phoenix, AZ 86072-2025

Report Date: 19-May-06

Date Received: 5-Apr-06

Arizona Lab License Number: AZ0626

| SAMPLE IDENTIFICATION | | LABORATORY NUMBER | AROCLOR | RESULTS |
|---------------------------|------------------------------------|-------------------|---------|---------|
| S/N: 90910 CO#: 48467 | 12317 Date Analyzed: 04/27/2006 | 136471-081 | | <1 ppm |
| S/N: 90908 CO#: 48469 | 12317 Date Analyzed: 04/27/2006 | 136471-082 | | <1 ppm |
| S/N: 90907 CO#: 48470 | 12317 Date Analyzed: 04/27/2006 | 136471-083 | | <1 ppm |
| S/N: 90917 CO#: 48472 | 12317 Date Analyzed: 04/27/2006 | 136471-084 | | <1 ppm |
| S/N: 90920 CO#: 48473 | 12317 Date Analyzed: 04/27/2006 | 136471-085 | | <1 ppm |
| S/N: 100346 CO#: 48477 | 12317 Date Analyzed: 04/27/2006 | 136471-086 | | <1 ppm |
| S/N: 90919 CO#: 48478 | 12317 Date Analyzed: 04/27/2006 | 136471-087 | | <1 ppm |
| S/N: 99179 CO#: 48479 | 12317 Date Analyzed: 04/27/2006 | 136471-088 | | <1 ppm |
| S/N: 102333 CO#: 48480 | 12317 Date Analyzed: 04/27/2006 | 136471-089 | | <1 ppm |
| S/N: 45058 CO#: 48482 | 12317 Date Analyzed: 04/27/2006 | 136471-090 | 1260 | 31 ppm |

Alternative Technologies, Inc., (ATI) shall assume no liability or responsibility, nor imply or express any warranty or other security against client loss of production, operation, profitability, or other loss, regardless of circumstances, beyond the cost of re-analysis by ATI.

Approved by: _____



TEST RESULTS

Alternative Technologies, Inc.
12350 River Ridge Blvd.
Burnsville, MN 55337
Telephone (800) 255-8656 or (952) 894-3455

PCB CONTENT USEPA METHOD 8082

Linda Johnson
Salt River Project
P.O. Box 52025, XCT310
Phoenix, AZ 86072-2025

Report Date: 19-May-06

Date Received: 5-Apr-06

Arizona Lab License Number: AZ0626

| SAMPLE IDENTIFICATION | | LABORATORY NUMBER | AROCLOLOR | RESULTS |
|--------------------------|------------------------------------|-------------------|-----------|---------|
| S/N: 85828 CO#: 48484 | 12317 Date Analyzed: 04/27/2006 | 136471-091 | | <1 ppm |
| S/N: 88405 CO#: 48460 | 12317 Date Analyzed: 04/27/2006 | 136471-092 | | <1 ppm |
| S/N: 88406 CO#: 48461 | 12317 Date Analyzed: 04/27/2006 | 136471-093 | | <1 ppm |
| S/N: 88355 CO#: 48462 | 12317 Date Analyzed: 04/27/2006 | 136471-094 | | <1 ppm |
| S/N: 88311 CO#: 48463 | 12317 Date Analyzed: 04/27/2006 | 136471-095 | | <1 ppm |
| S/N: 88356 CO#: 48464 | 12317 Date Analyzed: 04/27/2006 | 136471-096 | | <1 ppm |
| S/N: 88346 CO#: 48465 | 12317 Date Analyzed: 04/27/2006 | 136471-097 | | <1 ppm |
| S/N: 87201 CO#: 48466 | 12317 Date Analyzed: 04/27/2006 | 136471-098 | | <1 ppm |
| S/N: 71662 CO#: 48163 | 12317 Date Analyzed: 04/27/2006 | 136471-099 | | <1 ppm |

Alternative Technologies, Inc., (ATI) shall assume no liability or responsibility, nor imply or express any warranty or other security against client loss of production, operation, profitability, or other loss, regardless of circumstances, beyond the cost of re-analysis by ATI.

Approved by: _____





POST OFFICE BOX 52025
PHOENIX, ARIZONA 85072-2025

CHAIN OF CUSTODY

PAGE ___ OF ___

Environmental Services
Lab & Field Services Division
Ph (602) 236-4141
Fax (602) 236-4144

MAT# A611NW

| PROJECT QUALITY LINE PCB'S | | | CHARGE No | | | COST CENTER | | | ANALYSIS REQUESTED | | |
|----------------------------|-----------------------|-------------|------------|-----------------|-----|-------------|--|--|--------------------|--|--|
| YANCY GILL | | | 2-9-5013-0 | | | 83133 | | | | | |
| PROJECT MANAGER | | PHONE | | | | | | | | | |
| YANCY GILL | | X 8474 | | | | | | | | | |
| SAMPLE ID | SRP # and/or SERIAL # | SAMPLE DATE | LAB ID No. | # OF CONTAINERS | PCB | COMMENTS | | | | | |
| 40512 | 45121 | 1-30-06 | 12319-01 | | Y | | | | | | |
| 40514 | 81777 | 1-31-06 | 02 | | Y | | | | | | |
| 40515 | 33998 | 1-30-06 | 03 | | Y | | | | | | |
| 40517 | 30820 | 1-31-06 | 04 | | Y | | | | | | |
| 40518 | 27327 | 1-31-06 | 05 | | Y | | | | | | |
| 40520 | 88902 | 1-31-06 | 06 | | Y | | | | | | |
| 40521 | 61223 | 1-31-06 | 07 | | Y | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |

RELEAQUISHED BY: (SIGNATURE)
James H. Yancy

RELEAQUISHED BY: (SIGNATURE)
Shirley Yunceman

WITHIN 30 BOXES

| DATE | TIME | RECEIVED BY: (SIGNATURE) | DATE | TIME |
|---------|------|--------------------------|---------|------|
| 2-15-06 | | <i>Shirley Yunceman</i> | 2/15/06 | |
| 3/28/06 | | <i>Leopold</i> | 4/5/06 | |



POST OFFICE BOX 52025
PHOENIX, ARIZONA 85072-2025

MADP# CE108E

CHAIN OF CUSTODY

PAGE OF

Environmental Services
Lab & Field Services Division
Ph (602) 236-4141
Fax (602) 236-4144

| PROJECT | | CHARGE No | COST CENTER | | ANALYSIS REQUESTED | |
|-------------------------------|-----------------------|-------------|--------------------------|---------|--------------------|-----|
| QUALITY LINE PCB'S | | 2-9-5013-0 | 83133 | | # OF CONTAINERS | PCB |
| PROJECT MANAGER | | | PHONE | | | |
| YANCY GILL | | | x 8474 | | | |
| SAMPLE ID | SRP # and/or SERIAL # | SAMPLE DATE | LAB ID No. | | | |
| 48112 | 63352 | 2-1-06 | 12319-08 | | Y | |
| 48114 | 90853 | 2-1-06 | " 09 | | Y | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| REQUISITIONED BY: (SIGNATURE) | DATE | TIME | RECEIVED BY: (SIGNATURE) | DATE | TIME | |
| <i>[Signature]</i> | 2-15-06 | | <i>[Signature]</i> | 2/15/06 | | |
| REQUISITIONED BY: (SIGNATURE) | DATE | TIME | RECEIVED BY: (SIGNATURE) | DATE | TIME | |
| <i>[Signature]</i> | 3/28/06 | | <i>[Signature]</i> | 4/15/06 | | |

WIKIE Box 20



POST OFFICE BOX 52025
 PHOENIX, ARIZONA 85072-2025

CHAIN OF CUSTODY

Environmental Services
 Lab & Field Services Division
 Ph (602) 236-4141
 Fax (602) 236-4144

MAP# CE10NE

PAGE _____ OF _____

| PROJECT | | QUALITY LINE PCB'S | CHARGE No | COST CENTER | PHONE | ANALYSIS REQUESTED | |
|-------------------------|-----------------------|--------------------|-------------------------|-----------------|--------|--------------------|----------|
| PROJECT MANAGER | | YANCY GILL | | 83133 | X 8474 | PCB | COMMENTS |
| SAMPLE ID | SRP # and of SERIAL # | SAMPLE DATE | LAB ID No. | # OF CONTAINERS | Y | | |
| 4811 | 67453 | 2-1-06 | 12319-10 | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| REMOVED BY: (SIGNATURE) | DATE | TIME | REMOVED BY: (SIGNATURE) | DATE | TIME | | |
| <i>[Signature]</i> | 2-15-06 | | <i>[Signature]</i> | 2/15/06 | | | |
| REMOVED BY: (SIGNATURE) | DATE | TIME | REMOVED BY: (SIGNATURE) | DATE | TIME | | |
| <i>[Signature]</i> | 3-28-06 | | <i>[Signature]</i> | 4/5/06 | | | |

Middle Box 20



CHAIN OF CUSTODY

POST OFFICE BOX 52025
PHOENIX, ARIZONA 85072-2025

MAP# CEIDNW

PAGE ___ OF ___

Environmental Services
Lab & Field Services Division
Ph (602) 236-4141
Fax (602) 236-4144

PROJECT QUALITY LINE PCB'S

CHARGE No 2-9-5013-0

COST CENTER 83133

PROJECT MANAGER YANCY GILL

PHONE x 8474

SAMPLE ID SRP # and or SERIAL #

SAMPLE DATE

LAB ID No.

OF CONTAINERS

PCB

ANALYSIS REQUESTED

COMMENTS

48109

100698

2-1-06

12319-13

Y

Y

Y

Y

Y

Y

Y

Y

Y

Y

Y

Y

Y

Y

Y

Y

Y

Y

Y

Y

Y

Y

Y

Y

Y

Y

Y

Y

Y

Y

Y

Y

RELINQUISHED BY: (SIGNATURE)
and Julie

DATE 2-15-06

TIME

RECEIVED BY: (SIGNATURE)
Shirley Hemman

DATE 3/15/06

TIME

RELINQUISHED BY: (SIGNATURE)
Shirley Hemman

DATE 3-28-06

TIME

RECEIVED BY: (SIGNATURE)
Debra

DATE 4/5/06

TIME

Middle Box



POST OFFICE BOX 52025
PHOENIX, ARIZONA 85072-2025

MAAT# CFSONE

CHAIN OF CUSTODY

PAGE 1 OF 1

Environmental Services
Lab & Field Services Division
Ph (602) 236-4141
Fax (602) 236-4144

| PROJECT QUALITY LINE PCB'S | PROJECT MANAGER | CHARGE NO | COST CENTER | PHONE | # OF CONTAINERS | ANALYSIS REQUESTED | |
|----------------------------|-----------------|------------|-------------|--------|-----------------|--------------------|----------|
| | | | | | | PCB | COMMENTS |
| 48107 | YANCY GILL | 2-9-5013-0 | 83133 | X 8474 | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |

RELINQUISHED BY: (SIGNATURE) *[Signature]* DATE *2-15-06* TIME

RELINQUISHED BY: (SIGNATURE) *[Signature]* DATE *3/28/06* TIME

RECEIVED BY: (SIGNATURE) *[Signature]* DATE *2/15/06* TIME

RECEIVED BY: (SIGNATURE) *[Signature]* DATE *4/15/06* TIME

Middle, Bobo



POST OFFICE BOX 52025
PHOENIX, ARIZONA 85072-2025

MAP# AE-2008E

CHAIN OF CUSTODY

PAGE OF

Environmental Services
Lab & Field Services Division
Ph (602) 236-4141
Fax (602) 236-4144

| | | | | | | | | | |
|-------------------------------|-----------------------|-------------------------|--------------------------|----------------------|------|-----------------|----------|--------------------|------|
| PROJECT QUALITY LINE PCB'S | | CHARGE No 2-9-5013-0 | | COST CENTER 83133 | | # OF CONTAINERS | | ANALYSIS REQUESTED | |
| PROJECT MANAGER YANCY GILL | | PHONE X 8474 | | LAB ID No. | | | | | |
| SAMPLE ID | SRP # and/or SERIAL # | SAMPLE DATE | LAB ID No. | | | | | | |
| 480103 | 37243 | 2-2-06 | 12317-18 | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| RELINQUISHED BY: (SIGNATURE) | DATE | TIME | RECEIVED BY: (SIGNATURE) | DATE | TIME | PCB | COMMENTS | DATE | TIME |
| <i>Yancy Gill</i> | 2-15-06 | | <i>Shirley Kreneman</i> | 2/15/06 | | Y | | 4/15/06 | |
| RELINQUISHED BY: (SIGNATURE) | DATE | TIME | RECEIVED BY: (SIGNATURE) | DATE | TIME | PCB | COMMENTS | DATE | TIME |
| <i>Shirley Kreneman</i> | 3/28/06 | | <i>Leopold</i> | 4/15/06 | | Y | | | |

Mittle, Box 20



POST OFFICE BOX 52025
PHOENIX, ARIZONA 85072-2025

MAP# AE 198W

CHAIN OF CUSTODY

PAGE 1 OF 1

Environmental Services
Lab & Field Services Division
Ph (602) 236-4141
Fax (602) 236-4144

| PROJECT | | QUALITY LINE PCB'S | CHARGE No | COST CENTER | PHONE | ANALYSIS REQUESTED | |
|------------------------------|-----------------------|--------------------|--------------------------|-----------------|--------|--------------------|----------|
| PROJECT MANAGER | | YANCY GILL | | 83133 | X 8474 | PCB | COMMENTS |
| SAMPLE ID | SRP # and or SERIAL # | SAMPLE DATE | LAB ID No. | # OF CONTAINERS | | | |
| 48002 | 40649 | 2-2-06 | 12319-19 | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| | | | | | Y | | |
| RELINQUISHED BY: (SIGNATURE) | DATE | TIME | RECEIVED BY: (SIGNATURE) | DATE | TIME | DATE | TIME |
| <i>Yancy Gill</i> | 2-15-06 | | <i>Elaine Hummer</i> | 2/15/06 | | 2/15/06 | |
| RELINQUISHED BY: (SIGNATURE) | DATE | TIME | RECEIVED BY: (SIGNATURE) | DATE | TIME | DATE | TIME |
| <i>Elaine Hummer</i> | 3/28/06 | | <i>Leeper</i> | 4/15/06 | | 4/15/06 | |

Maple Box 20



POST OFFICE BOX 52025
PHOENIX, ARIZONA 85072-2025

CHAIN OF CUSTODY

PAGE ____ OF ____

Environmental Services
Lab & Field Services Division
Ph (602) 236-4141
Fax (602) 236-4144

PROJECT QUALITY LINE PCB'S CHARGE No 2-9-5013-0 COST CENTER 83133

PROJECT MANAGER YANCY GILL PHONE X 8474

SAMPLE ID SRP # and or SERIAL # SAMPLE DATE LAB ID No. # OF CONTAINERS PCB ANALYSIS REQUESTED COMMENTS

480104 30489 2-2-06 12319-20 Y Y

480105 94037 2-2-06 11 21 Y Y

Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y

[Signature]
RELINQUISHED BY: (SIGNATURE)

DATE 7-15-06 TIME

RECEIVED BY: (SIGNATURE)
Shane Nunez

DATE 2/5/06 TIME

RELINQUISHED BY: (SIGNATURE) DATE 3/28/06 TIME RECEIVED BY: (SIGNATURE) DATE 2/5/06 TIME

Middle 870220



POST OFFICE BOX 52025
PHOENIX, ARIZONA 85072-2025

CHAIN OF CUSTODY

PAGE _____ OF _____

Environmental Services
Lab & Field Services Division
Ph (602) 236-4141
Fax (602) 236-4144

MAP# AD 24 NW

PROJECT QUALITY LINE PCB'S CHARGE No 2-9-5013-0

COST CENTER 83133

ANALYSIS REQUESTED

PROJECT MANAGER YANCY GILL

PHONE X 8474

| SAMPLE ID | SRP # and or SERIAL # | SAMPLE DATE | LAB ID No. | # OF CONTAINERS | PCB | COMMENTS |
|-----------|-----------------------|-------------|------------|-----------------|-----|----------|
|-----------|-----------------------|-------------|------------|-----------------|-----|----------|

| | | | | | | |
|--------|--------|--------|----------|--|---|--|
| 48308 | 67927 | 2-6-06 | 12319-22 | | Y | |
| 48310 | 93042 | 2-6-06 | 23 | | Y | |
| 48311 | 99699 | 2-6-06 | 24 | | Y | |
| 48312 | 99698 | 2-6-06 | 25 | | Y | |
| 48313 | 90848 | 2-6-06 | 26 | | Y | |
| 48314 | 90926 | 2-6-06 | 27 | | Y | |
| 48315 | 90849 | 2-6-06 | 28 | | Y | |
| 48316 | 100200 | 2-6-06 | 29 | | Y | |
| 48317 | 102968 | 2-6-06 | 30 | | Y | |
| 48318 | 96331 | 2-6-06 | 31 | | Y | |
| 48319 | 100390 | 2-6-06 | 32 | | Y | |
| 48320 | 100765 | 2-6-06 | 33 | | Y | |
| 48321 | 90795 | 2-6-06 | 34 | | Y | |
| 48322 | 88359 | 2-6-06 | 35 | | Y | |
| 483224 | 99680 | 2-6-06 | 36 | | Y | |
| 48325 | 99678 | 2-6-06 | 37 | | Y | |
| 48322 | 99399 | 2-6-06 | 38 | | Y | |

REMOVED BY: (SIGNATURE) _____ DATE _____ TIME _____

RECEIVED BY: (SIGNATURE) *Shirine Ahumani* DATE *3/15/06* TIME _____

REMOVED BY: (SIGNATURE) _____ DATE _____ TIME _____

RECEIVED BY: (SIGNATURE) *Shirine Ahumani* DATE *4/5/06* TIME _____

N. Mills 2-9-70



CHAIN OF CUSTODY
PAGE ____ OF ____

Environmental Services
Lab & Field Services Division
Ph (602) 236-4141
Fax (602) 236-4144

POST OFFICE BOX 52025
PHOENIX, ARIZONA 85072-2025

MART ADZONE

PROJECT QUALITY LINE PCB'S CHARGE NO 2-9-5013-0

COST CENTER 83133

PROJECT MANAGER YANCY GILL PHONE X 8474

ANALYSIS REQUESTED

| SAMPLE ID | SRP # and or SERIAL # | SAMPLE DATE | LAB ID No. | # OF CONTAINERS | ANALYSIS REQUESTED | |
|------------------------------|-----------------------|-------------|--------------------------|-----------------|--------------------|----------|
| | | | | | PCB | COMMENTS |
| 48295 | 86493 | 2-6-06 | 12319 - 39 | | Y | |
| 482910 | 92132 | 2-6-06 | | | Y | |
| 48297 | 94033 | 2-6-06 | | | Y | |
| 48299 | 85901 | 2-6-06 | | | Y | |
| 48301 | 97946 | 2-6-06 | | | Y | |
| 48302 | 92211 | 2-6-06 | | | Y | |
| 48303 | 84768 | 2-6-06 | | | Y | |
| 48304 | 84762 | 2-6-06 | | | Y | |
| 48305 | 84770 | 2-6-06 | | | Y | |
| 48306 | 98078 | 2-6-06 | | | Y | |
| | | | | | Y | |
| | | | | | Y | |
| | | | | | Y | |
| | | | | | Y | |
| | | | | | Y | |
| | | | | | Y | |
| | | | | | Y | |
| | | | | | Y | |
| | | | | | Y | |
| | | | | | Y | |
| | | | | | Y | |
| | | | | | Y | |
| RELINQUISHED BY: (SIGNATURE) | DATE | TIME | RECEIVED BY: (SIGNATURE) | DATE | TIME | |
| <i>Yancy Gill</i> | 2-15-06 | | <i>Shane Aumema</i> | 2/15/06 | | |
| RELINQUISHED BY: (SIGNATURE) | DATE | TIME | RECEIVED BY: (SIGNATURE) | DATE | TIME | |
| <i>Shane Aumema</i> | 3/28/06 | | <i>Wagner</i> | 4/5/06 | | |

11 N. Hill Road



POST OFFICE BOX 52025
PHOENIX, ARIZONA 85072-2025

MAR# CE21NE

CHAIN OF CUSTODY

PAGE _____ OF _____

Environmental Services
Lab & Field Services Division
Ph (602) 236-4141
Fax (602) 236-4144

| PROJECT | | CHARGE No | COST CENTER | PHONE | # OF CONTAINERS | ANALYSIS REQUESTED | |
|---|---------|-----------|--|---------|-----------------|--------------------|----------|
| PROJECT MANAGER | | | 83133 | X 8474 | | PCB | COMMENTS |
| 48143 | 62733 | 1-6-06 | 12319 - 49 | Y | | | |
| 48144 | 78502 | 2-6-06 | 56 | Y | | | |
| 48145 | 79184 | 2-6-06 | 51 | Y | | | |
| 48140 | 99915 | 2-6-06 | 52 | Y | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| REMOUNISHED BY: (SIGNATURE) <i>[Signature]</i> | DATE | TIME | RECEIVED BY: (SIGNATURE) <i>[Signature]</i> | DATE | TIME | DATE | TIME |
| REMOUNISHED BY: (SIGNATURE) <i>[Signature]</i> | 2-15-06 | | RECEIVED BY: (SIGNATURE) <i>[Signature]</i> | 2/15/06 | | 4/15/06 | |
| <i>Mitchko, Box 20</i> | 3/18/06 | | <i>[Signature]</i> | | | | |



POST OFFICE BOX 52025
PHOENIX, ARIZONA 85012-2025

SE

CHAIN OF CUSTODY

PAGE _____ OF _____

Environmental Services
Lab & Field Services Division
Ph (602) 236-4141
Fax (602) 236-4144

PROJECT QUALITY LINE PCB'S CHARGE No. 2-9-5013-0 COST CENTER 83133

PROJECT MANAGER YANCY GILL PHONE X 8474

SAMPLE ID SRP # and/or SERIAL # SAMPLE DATE LAB ID No. # OF CONTAINERS

48137 87067 2-6-06 12319-19 Y

Y

Y

Y

Y

Y

Y

Y

Y

Y

Y

Y

Y

Y

Y

RECEIVED BY: (SIGNATURE) RECEIVED BY: (SIGNATURE)

3/28/06 2/15/06

3/28/06 2/15/06

Michelle Max 20

