

TEST RESULTS

Alternative Technologies, Inc.

12350 River Ridge Blvd.
Burnsville, MN 55337
Telephone (800) 255-8656 or (952) 894-3455

PCB CONTENT USEPA METHOD 8082, 3580/3550, 3665

David Fischer
Salt River Project
P.O. Box 52025 MS-XCT329
Phoenix, AZ 85072-2025

Report Date: 7-Jun-13

Date Received: 31-May-13

Date Analyzed: 6-Jun-13

Arizona Lab License Number: AZ0626

SAMPLE IDENTIFICATION		LABORATORY NUMBER	AROCLOR	RESULTS
S/N: D903337 CO#: 1TGI-XF-2001	TRN FORTUNE MESQUITE GS	176008-001		<1 ppm
S/N: G12137-3 CO#: 2APC-XF-21	TRN PIONEER MESQUITE GS	176008-002		<1 ppm
S/N: G12137-4 CO#: 2APC-XF-22	TRN PIONEER MESQUITE GS	176008-003		<1 ppm
S/N: G12138-4 CO#: 2APC-XF-25	TRN PIONEER MESQUITE GS	176008-004		<1 ppm
S/N: G12138-3 CO#: 2APC-XF-26	TRN PIONEER MESQUITE GS	176008-005		<1 ppm
S/N: HB11034-002 CO#: 2APD-XF-2A	TRN ABB MESQUITE GS	176008-006		<1 ppm
S/N: HB11033-002 CO#: 2APD-XF-2B	TRN ABB MESQUITE GS	176008-007		<1 ppm
S/N: 12060TN0004 CO#: 2GTB-XF-4001	TRN FORTUNE MESQUITE GS	176008-008		<1 ppm
S/N: D903338 CO#: 2GTI-XF-5001	TRN FORTUNE MESQUITE GS	176008-009		<1 ppm
S/N: D903339 CO#: 2TGI-XF-6001	TRN FORTUNE MESQUITE GS	176008-010		<1 ppm

Alternative Technologies, Inc., (ATI) shall assume no liability or responsibility, nor imply or express any warranty or other security against client loss of production, operation, profitability, or other loss, regardless of circumstances, beyond the cost of re-analysis by ATI.