

TEST RESULTS

Alternative Technologies, Inc.
 12350 River Ridge Blvd.
 Burnsville, MN 55337
 Telephone (800) 255-8656 or (952) 894-3455

PCB CONTENT USEPA METHOD 8082, 3580/3550, 3665

Linda Johnson
 Salt River Project
 P.O. Box 52025, XCT310
 Phoenix, AZ 86072-2025



Report Date: 7-Aug-06

Date Received: 28-Jun-06

Arizona Lab License Number: AZ0626

SAMPLE IDENTIFICATION		LABORATORY NUMBER	AROCOLOR	RESULTS
S/N: 99990 CO#: 53911	12521 Date Analyzed: 08/02/2006	137729-001		<1 ppm
S/N: 101635 CO#: 53912	12521 Date Analyzed: 08/02/2006	137729-002		<1 ppm
S/N: 101622 CO#: 53913	12521 Date Analyzed: 08/02/2006	137729-003		<1 ppm
S/N: 101625 CO#: 53914	12521 Date Analyzed: 08/02/2006	137729-004		<1 ppm
S/N: 103315 CO#: 53915	12521 Date Analyzed: 08/02/2006	137729-005		<1 ppm
S/N: 90865 CO#: 53916	12521 Date Analyzed: 08/02/2006	137729-006		<1 ppm
S/N: 90815 CO#: 53917	12521 Date Analyzed: 08/02/2006	137729-007		<1 ppm
S/N: 90866 CO#: 53918	12521 Date Analyzed: 08/02/2006	137729-008		<1 ppm
S/N: 90864 CO#: 53919	12521 Date Analyzed: 08/02/2006	137729-009		<1 ppm
S/N: 102531 CO#: 53920	12521 Date Analyzed: 08/02/2006	137729-010		<1 ppm

Alternative Technologies, Inc., (ATI) shall assume no liability or responsibility, nor imply or express any warranty or other security against client loss of production, operation, profitability, or other loss, regardless of circumstances, beyond the cost of re-analysis by ATI.

Approved by: _____

TEST RESULTS

Alternative Technologies, Inc.

12350 River Ridge Blvd.
Burnsville, MN 55337
Telephone (800) 255-8656 or (952) 894-3455

PCB CONTENT USEPA METHOD 8082, 3580/3550, 3665

Linda Johnson
Salt River Project
P.O. Box 52025, XCT310
Phoenix, AZ 86072-2025

Report Date: 7-Aug-06

Date Received: 28-Jun-06

Arizona Lab License Number: AZ0626

SAMPLE IDENTIFICATION		LABORATORY NUMBER	AROCLOR	RESULTS
S/N: 102606 CO#: 53921	12521 Date Analyzed: 08/02/2006	137729-011		<1 ppm
S/N: 102530 CO#: 53922	12521 Date Analyzed: 08/02/2006	137729-012		<1 ppm
S/N: 102602 CO#: 53923	12521 Date Analyzed: 08/02/2006	137729-013		<1 ppm
S/N: 98964 CO#: 54591	12521 Date Analyzed: 08/02/2006	137729-014		<1 ppm
S/N: 90990 CO#: 54592	12521 Date Analyzed: 08/02/2006	137729-015		<1 ppm
S/N: 90992 CO#: 54593	12521 Date Analyzed: 08/02/2006	137729-016		<1 ppm
S/N: 90988 CO#: 54594	12521 Date Analyzed: 08/02/2006	137729-017		<1 ppm
S/N: 90964 CO#: 54595	12521 Date Analyzed: 08/02/2006	137729-018		<1 ppm
S/N: 90893 CO#: 54596	12521 Date Analyzed: 08/02/2006	137729-019		<1 ppm
S/N: 98969 CO#: 54597	12521 Date Analyzed: 08/02/2006	137729-020		<1 ppm

Alternative Technologies, Inc., (ATI) shall assume no liability or responsibility, nor imply or express any warranty or other security against client loss of production, operation, profitability, or other loss, regardless of circumstances, beyond the cost of re-analysis by ATI.

Approved by: _____



TEST RESULTS

Alternative Technologies, Inc.

12350 River Ridge Blvd.

Burnsville, MN 55337

Telephone (800) 255-8656 or (952) 894-3455

PCB CONTENT USEPA METHOD 8082, 3580/3550, 3665

Linda Johnson
Salt River Project
P.O. Box 52025, XCT310
Phoenix, AZ 86072-2025

Report Date: 7-Aug-06

Date Received: 28-Jun-06

Arizona Lab License Number: AZ0626

SAMPLE IDENTIFICATION		LABORATORY NUMBER	AROCOLOR	RESULTS
S/N: 90962 CO#: 54598	12521 Date Analyzed: 08/02/2006	137729-021		<1 ppm
S/N: 98949 CO#: 54599	12521 Date Analyzed: 08/02/2006	137729-022		<1 ppm
S/N: 90894 CO#: 54600	12521 Date Analyzed: 08/02/2006	137729-023		<1 ppm
S/N: 90995 CO#: 54601	12521 Date Analyzed: 08/02/2006	137729-024		<1 ppm
S/N: 98948 CO#: 54602	12521 Date Analyzed: 08/02/2006	137729-025		<1 ppm
S/N: 98944 CO#: 54603	12521 Date Analyzed: 08/02/2006	137729-026		<1 ppm
S/N: 90989 CO#: 54604	12521 Date Analyzed: 08/02/2006	137729-027		<1 ppm
S/N: 90880 CO#: 54605	12521 Date Analyzed: 08/02/2006	137729-028		<1 ppm
S/N: 90991 CO#: 54606	12521 Date Analyzed: 08/02/2006	137729-029		<1 ppm
S/N: 98945 CO#: 54607	12521 Date Analyzed: 08/02/2006	137729-030		<1 ppm

Alternative Technologies, Inc., (ATI) shall assume no liability or responsibility, nor imply or express any warranty or other security against client loss of production, operation, profitability, or other loss, regardless of circumstances, beyond the cost of re-analysis by ATI.

Approved by: _____



TEST RESULTS

Alternative Technologies, Inc.

12350 River Ridge Blvd.

Burnsville, MN 55337

Telephone (800) 255-8656 or (952) 894-3455

PCB CONTENT USEPA METHOD 8082, 3580/3550, 3665

Linda Johnson
Salt River Project
P.O. Box 52025, XCT310
Phoenix, AZ 86072-2025

Report Date: 7-Aug-06

Date Received: 28-Jun-06

Arizona Lab License Number: AZ0626

SAMPLE IDENTIFICATION		LABORATORY NUMBER	AROCOR	RESULTS
S/N: 90881 CO#: 54608	12521 Date Analyzed: 08/02/2006	137729-031		<1 ppm
S/N: 98950 CO#: 54609	12521 Date Analyzed: 08/02/2006	137729-032		<1 ppm
S/N: 98942 CO#: 54610	12521 Date Analyzed: 08/02/2006	137729-033		<1 ppm
S/N: 84937 CO#: 54455	12521 Date Analyzed: 08/02/2006	137729-034		<1 ppm
S/N: 84928 CO#: 54456	12521 Date Analyzed: 08/02/2006	137729-035		<1 ppm
S/N: 102477 CO#: 54457	12521 Date Analyzed: 08/02/2006	137729-036		<1 ppm
S/N: 84930 CO#: 54458	12521 Date Analyzed: 08/02/2006	137729-037		<1 ppm
S/N: 84932 CO#: 54459	12521 Date Analyzed: 08/02/2006	137729-038		<1 ppm
S/N: 84980 CO#: 54460	12521 Date Analyzed: 08/02/2006	137729-039		<1 ppm
S/N: 100596 CO#: 54461	12521 Date Analyzed: 08/02/2006	137729-040		<1 ppm

Alternative Technologies, Inc., (ATI) shall assume no liability or responsibility, nor imply or express any warranty or other security against client loss of production, operation, profitability, or other loss, regardless of circumstances, beyond the cost of re-analysis by ATI.

Approved by: _____



TEST RESULTS

Alternative Technologies, Inc.

12350 River Ridge Blvd.
Burnsville, MN 55337
Telephone (800) 255-8656 or (952) 894-3455

PCB CONTENT USEPA METHOD 8082, 3580/3550, 3665

Linda Johnson
Salt River Project
P.O. Box 52025, XCT310
Phoenix, AZ 86072-2025

Report Date: 7-Aug-06

Date Received: 28-Jun-06

Arizona Lab License Number: AZ0626

SAMPLE IDENTIFICATION		LABORATORY NUMBER	AROCLOR	RESULTS
S/N: 84969 CO#: 54462	12521 Date Analyzed: 08/02/2006	137729-041		<1 ppm
S/N: 84979 CO#: 54463	12521 Date Analyzed: 08/02/2006	137729-042		<1 ppm
S/N: 84976 CO#: 54464	12521 Date Analyzed: 08/02/2006	137729-043		<1 ppm
S/N: 84933 CO#: 54465	12521 Date Analyzed: 08/02/2006	137729-044		<1 ppm
S/N: 99100 CO#: 54466	12521 Date Analyzed: 08/02/2006	137729-045		<1 ppm
S/N: 90211 CO#: 54611	12521 Date Analyzed: 08/02/2006	137729-046		<1 ppm
S/N: 99719 CO#: 54612	12521 Date Analyzed: 08/02/2006	137729-047		<1 ppm
S/N: 95261 CO#: 54613	12521 Date Analyzed: 08/02/2006	137729-048		<1 ppm
S/N: 103316 CO#: 54614	12521 Date Analyzed: 08/02/2006	137729-049		<1 ppm
S/N: 97627 CO#: 53934	12521 Date Analyzed: 08/02/2006	137729-050		<1 ppm

Alternative Technologies, Inc., (ATI) shall assume no liability or responsibility, nor imply or express any warranty or other security against client loss of production, operation, profitability, or other loss, regardless of circumstances, beyond the cost of re-analysis by ATI.

Approved by: _____



TEST RESULTS

Alternative Technologies, Inc.

12350 River Ridge Blvd.

Burnsville, MN 55337

Telephone (800) 255-8656 or (952) 894-3455

PCB CONTENT USEPA METHOD 8082, 3580/3550, 3665

Linda Johnson
Salt River Project
P.O. Box 52025, XCT310
Phoenix, AZ 86072-2025

Report Date: 7-Aug-06

Date Received: 28-Jun-06

Arizona Lab License Number: AZ0626

SAMPLE IDENTIFICATION		LABORATORY NUMBER	AROCOR	RESULTS
S/N: 101622 CO#: 53935	12521 Date Analyzed: 08/02/2006	137729-051		<1 ppm
S/N: 101625 CO#: 54175	12521 Date Analyzed: 08/02/2006	137729-052		<1 ppm
S/N: 98361 CO#: 54589	12521 Date Analyzed: 08/02/2006	137729-053		<1 ppm
S/N: 96807 CO#: 54590	12521 Date Analyzed: 08/02/2006	137729-054	1254/60	8 ppm
S/N: 101148 CO#: 52294	12521 Date Analyzed: 08/02/2006	137729-055		<1 ppm
S/N: 94910 CO#: 54475	12521 Date Analyzed: 08/02/2006	137729-056		<1 ppm
S/N: 91120 CO#: 54476	12521 Date Analyzed: 08/02/2006	137729-057		<1 ppm
S/N: 93637 CO#: 54477	12521 Date Analyzed: 08/03/2006	137729-058		<1 ppm
S/N: 93623 CO#: 54478	12521 Date Analyzed: 08/03/2006	137729-059		<1 ppm
S/N: 95693 CO#: 54479	12521 Date Analyzed: 08/03/2006	137729-060		<1 ppm

Alternative Technologies, Inc., (ATI) shall assume no liability or responsibility, nor imply or express any warranty or other security against client loss of production, operation, profitability, or other loss, regardless of circumstances, beyond the cost of re-analysis by ATI.

Approved by: _____



TEST RESULTS

Alternative Technologies, Inc.

12350 River Ridge Blvd.

Burnsville, MN 55337

Telephone (800) 255-8656 or (952) 894-3455

PCB CONTENT USEPA METHOD 8082, 3580/3550, 3665

Linda Johnson
Salt River Project
P.O. Box 52025, XCT310
Phoenix, AZ 86072-2025

Report Date: 7-Aug-06

Date Received: 28-Jun-06

Arizona Lab License Number: AZ0626

SAMPLE IDENTIFICATION		LABORATORY NUMBER	AROCOR	RESULTS
S/N: 93636 CO#: 54480	12521 Date Analyzed: 08/03/2006	137729-061		<1 ppm
S/N: 95791 CO#: 54481	12521 Date Analyzed: 08/03/2006	137729-062		<1 ppm
S/N: 95545 CO#: 54482	12521 Date Analyzed: 08/03/2006	137729-063		<1 ppm
S/N: 95546 CO#: 54483	12521 Date Analyzed: 08/03/2006	137729-064		<1 ppm
S/N: 102264 CO#: 54484	12521 Date Analyzed: 08/03/2006	137729-065		<1 ppm
S/N: 95544 CO#: 54485	12521 Date Analyzed: 08/03/2006	137729-066		<1 ppm
S/N: 97055 CO#: 54486	12521 Date Analyzed: 08/03/2006	137729-067		<1 ppm
S/N: 84172 CO#: 54487	12521 Date Analyzed: 08/03/2006	137729-068		<1 ppm
S/N: 91800 CO#: 54488	12521 Date Analyzed: 08/03/2006	137729-069		<1 ppm
S/N: 84185 CO#: 54489	12521 Date Analyzed: 08/03/2006	137729-070		<1 ppm

Alternative Technologies, Inc., (ATI) shall assume no liability or responsibility, nor imply or express any warranty or other security against client loss of production, operation, profitability, or other loss, regardless of circumstances, beyond the cost of re-analysis by ATI.

Approved by: _____



TEST RESULTS

Alternative Technologies, Inc.

12350 River Ridge Blvd.
Burnsville, MN 55337
Telephone (800) 255-8656 or (952) 894-3455

PCB CONTENT USEPA METHOD 8082, 3580/3550, 3665

Linda Johnson
Salt River Project
P.O. Box 52025, XCT310
Phoenix, AZ 86072-2025

Report Date: 7-Aug-06

Date Received: 28-Jun-06

Arizona Lab License Number: AZ0626

SAMPLE IDENTIFICATION		LABORATORY NUMBER	AROCLOR	RESULTS
S/N: 91083 CO#: 54490	12521 Date Analyzed: 08/03/2006	137729-071		<1 ppm
S/N: 91085 CO#: 54491	12521 Date Analyzed: 08/03/2006	137729-072		<1 ppm
S/N: 91084 CO#: 54492	12521 Date Analyzed: 08/03/2006	137729-073		<1 ppm
S/N: 84171 CO#: 54493	12521 Date Analyzed: 08/03/2006	137729-074	1254/60	16 ppm
S/N: 87116 CO#: 54494	12521 Date Analyzed: 08/03/2006	137729-075	1254/60	15 ppm
S/N: 92153 CO#: 54696	12521 Date Analyzed: 08/03/2006	137729-076		<1 ppm
S/N: 88298 CO#: 54697	12521 Date Analyzed: 08/03/2006	137729-077		<1 ppm
S/N: 102864 CO#: 54698	12521 Date Analyzed: 08/03/2006	137729-078		<1 ppm
S/N: 103252 CO#: 54735	12521 Date Analyzed: 08/03/2006	137729-079		<1 ppm
S/N: 102972 CO#: 54736	12521 Date Analyzed: 08/03/2006	137729-080		<1 ppm

Alternative Technologies, Inc., (ATI) shall assume no liability or responsibility, nor imply or express any warranty or other security against client loss of production, operation, profitability, or other loss, regardless of circumstances, beyond the cost of re-analysis by ATI.

Approved by: _____



TEST RESULTS

Alternative Technologies, Inc.

12350 River Ridge Blvd.
Burnsville, MN 55337
Telephone (800) 255-8656 or (952) 894-3455

PCB CONTENT USEPA METHOD 8082, 3580/3550, 3665

Linda Johnson
Salt River Project
P.O. Box 52025, XCT310
Phoenix, AZ 86072-2025

Report Date: 7-Aug-06

Date Received: 28-Jun-06

Arizona Lab License Number: AZ0626

SAMPLE IDENTIFICATION		LABORATORY NUMBER	AROCLOR	RESULTS
S/N: 103253 CO#: 54737	12521 Date Analyzed: 08/03/2006	137729-081		<1 ppm
S/N: 103218 CO#: 54738	12521 Date Analyzed: 08/03/2006	137729-082	1254/60	11 ppm
S/N: 85138 CO#: 54469	12521 Date Analyzed: 08/03/2006	137729-083		<1 ppm
S/N: 85136 CO#: 54470	12521 Date Analyzed: 08/03/2006	137729-084		<1 ppm
S/N: 85009 CO#: 54471	12521 Date Analyzed: 08/03/2006	137729-085		<1 ppm
S/N: 85159 CO#: 54472	12521 Date Analyzed: 08/03/2006	137729-086		<1 ppm
S/N: 85015 CO#: 54473	12521 Date Analyzed: 08/03/2006	137729-087		<1 ppm
S/N: 90330 CO#: 54474	12521 Date Analyzed: 08/03/2006	137729-088		<1 ppm
S/N: 100333 CO#: 52746	12521 Date Analyzed: 08/03/2006	137729-089		<1 ppm
S/N: 93084 CO#: 52747	12521 Date Analyzed: 08/03/2006	137729-090	1260	2 ppm

Alternative Technologies, Inc., (ATI) shall assume no liability or responsibility, nor imply or express any warranty or other security against client loss of production, operation, profitability, or other loss, regardless of circumstances, beyond the cost of re-analysis by ATI.

Approved by: _____



TEST RESULTS

Alternative Technologies, Inc.

12350 River Ridge Blvd.

Burnsville, MN 55337

Telephone (800) 255-8656 or (952) 894-3455

PCB CONTENT USEPA METHOD 8082, 3580/3550, 3665

Linda Johnson
Salt River Project
P.O. Box 52025, XCT310
Phoenix, AZ 86072-2025

Report Date: 7-Aug-06

Date Received: 28-Jun-06

Arizona Lab License Number: AZ0626

SAMPLE IDENTIFICATION		LABORATORY NUMBER	AROCOR	RESULTS
S/N: 66012 CO#: 52748	12521 Date Analyzed: 08/03/2006	137729-091	1242/60	58 ppm
S/N: 97472 CO#: 52751	12521 Date Analyzed: 08/03/2006	137729-092		<1 ppm
S/N: 44482 CO#: 52752	12521 Date Analyzed: 08/03/2006	137729-093	1254	3 ppm
S/N: 91915 CO#: 52753	12521 Date Analyzed: 08/03/2006	137729-094	1254/60	6 ppm
S/N: 82930 CO#: 52754	12521 Date Analyzed: 08/03/2006	137729-095		<1 ppm
S/N: 92438 CO#: 52755	12521 Date Analyzed: 08/03/2006	137729-096		<1 ppm
S/N: 44157 CO#: 52756	12521 Date Analyzed: 08/03/2006	137729-097	1260	394 ppm
S/N: 96007 CO#: 52735	12521 Date Analyzed: 08/03/2006	137729-098		<1 ppm
S/N: 72599 CO#: 52736	12521 Date Analyzed: 08/03/2006	137729-099		<1 ppm
S/N: 60736 CO#: 52737	12521 Date Analyzed: 08/03/2006	137729-100		<1 ppm

Alternative Technologies, Inc., (ATI) shall assume no liability or responsibility, nor imply or express any warranty or other security against client loss of production, operation, profitability, or other loss, regardless of circumstances, beyond the cost of re-analysis by ATI.

Approved by: _____





POST OFFICE BOX 52025
PHOENIX, ARIZONA 85072-2025

CHAIN OF CUSTODY

PAGE OF

MAD#CBZANE

Environmental Services
Lab & Field Services Division
Ph (602) 236-4141
Fax (602) 236-4144

PROJECT QUALITY LINE PCB'S PROJECT MANAGER	CHARGE NO	COST CENTER	PHONE	SRP # and or SERIAL #	SAMPLE DATE	LAB ID No.	# OF CONTAINERS	ANALYSIS REQUESTED	
								PCB	COMMENTS
YANCY GILL		83133	x 8474						
	54591	98964	3-27-06	12521-	14		Y		
	54592	90990	3-27-06		15		Y		
	54593	90992	3-27-06		16		Y		
	54594	90988	3-27-06		17		Y		
	54595	90964	3-27-06		18		Y		
	54596	90893	3-27-06		19		Y		
	54597	98969	3-27-06		20		Y		
	54598	90962	3-27-06		21		Y		
	54599	98949	3-27-06		22		Y		
	54600	90894	3-27-06		23		Y		
	54601	90995	3-27-06		24		Y		
	54602	98948	3-27-06		25		Y		
	54603	98944	3-27-06		26		Y		
	54604	90989	3-27-06		27		Y		
54605	90880	3-27-06		28		Y			
54606	90991	3-27-06		29		Y			
54607	98945	3-27-06		30		Y			
54608	90881	3-27-06		31		Y			
54609	98950	3-27-06		32		Y			
54610	98942	3-27-06		33		Y			
RELINQUISHED BY: (SIGNATURE)				RECEIVED BY: (SIGNATURE)				DATE	TIME
<i>Yancy Gill</i>				<i>John Beneman</i>				4/19/06	
RELINQUISHED BY: (SIGNATURE)				RECEIVED BY: (SIGNATURE)				DATE	TIME
<i>John Beneman</i>				<i>Weyner</i>				6/28/06	

TAD R-29



POST OFFICE BOX 52025
PHOENIX, ARIZONA 85072-2025

Environmental Services
Lab & Field Services Division
Ph (602) 236-4141
Fax (602) 236-4144

CHAIN OF CUSTODY

PAGE _____ OF _____

MRP# CB19SR

PROJECT QUALITY LINE PCB'S PROJECT MANAGER	CHARGE No 2-9-5013-0	COST CENTER 83133	PHONE x 8474		SRP # and or SERIAL #	LAB ID No.	# OF CONTAINERS	ANALYSIS REQUESTED	
			SAMPLE DATE	LAB ID No.				PCB	COMMENTS
54475	94910	3-28-06	12521-	56		1		Y	
54476	91120	3-28-06		59		1		Y	
54477	93637	3-28-06		58		1		Y	
54478	93623	3-28-06		59		1		Y	
54479	95693	3-28-06		60		1		Y	
54480	93636	3-28-06		61		1		Y	
54481	95791	3-28-06		62		1		Y	
54482	95545	3-28-06		63		1		Y	
54483	95546	3-28-06		64		1		Y	
54484	102264	3-28-06		65		1		Y	
54485	95544	3-28-06		66		1		Y	
54486	97055	3-28-06		67		1		Y	
54487	84172	3-28-06		68		1		Y	
54488	91800	3-28-06		69		1		Y	
54489	84185	3-28-06		70		1		Y	
54490	91083	3-28-06		71		1		Y	
54491	91085	3-28-06		72		1		Y	
54492	91084	3-28-06		73		1		Y	
RELINQUISHED BY: (SIGNATURE)					RECEIVED BY: (SIGNATURE)	DATE	TIME	DATE	TIME
<i>[Signature]</i>					Elaine Hummer	4/19/06		4/19/06	
RELINQUISHED BY: (SIGNATURE)					RECEIVED BY: (SIGNATURE)	DATE	TIME	DATE	TIME
<i>[Signature]</i>					Elaine Hummer	6/28/06		6/28/06	

TRD Box 32

